



PIÈCES DÉTACHÉES


Souffleur 56V

LB7650E



Repair Parts_Blower_4716 (LB7650E)

Index No.	Art. No.	Description	QTY in machine	Weight (g)	Size LxWxH (mm)
1	3680196001	Magnet Ring	1	18	16x16x28
2	5650519001	Rubber Gasket	4	2,4	20x9.9x8.9
3	2828754001	Ducted Set	1	525	146x146x260
4	3660088003	Knob-reset Spring	2	0,2	6x6x18
5	2828460002	Blow Tube Assembly	1	298	94x94x484
6	5610274003	Self Tapping Screw	1	0,8	5.6x5.6x18
7	5610294001	Tapping Screw	15	1,3	7x7x18
8	3132552001	Fan Baffle	1	80	169x166.5x78
9	5620176002	Screw With Washer	2	3	6x6x7.5
10	3660818001	Compression Spring	1	3,4	41x11x11
11	3131427001	Sliding Block	1	9,7	42x41x20
12	2831131001	Electric Assembly	1	200	100x80x50
13	3127498001	Power Pack Button	1	9,5	43x36.8x27.5
14	3127497001	Power Pack Button	1	5	42.5x24.5x11.4
15	3660013003	Spring1	1	1	9.9x9.9x25
16	3706375001	Hook	1	10,5	37x31x20





ISEKI France S.A.S - ZAC des Ribes
27, avenue des frères Montgolfier - CS 20024
63178 Aubière Cedex
Tél. 04 73 91 93 51 - Fax. 04 73 90 23 11
E-mail : info@iseki.fr - www.iseki.fr